

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020

For FAA Use Only

Office Identification

50 FSD017

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1,000 for each such violation (Section 901 Federal Aviation Act of 1958).

		•								
1. Aircraft		Make REPUBLICATION Model Serial No Nationality and Begistration Mark								
		Serial No.		Nationalit	nality and Registration Mark NSCSCS					
		•	n on registration cer	,	· · · · · · · · · · · · · · · · · · ·					
2. Owner		HEN REYSURRED DESIDENCE days BUILD BY STUDIES RULLER RULLE								<u></u> ለጋረገ
a living stil objected denoted and hook waterny feath of										
នៅ វិទៅនៃខេត្តខ្លួនរៀវ ១៤៤៤ 3 EFONFAA Use Only ដែលផ្សាំ ១៩៤៤ខ្លែង ប្រការ ប្រតិស្មីយុទ្ធខ្លួន										
accordance with AC43.13-1A. Chapter 2. Section 3, and Panapaph d Demaged area was removed and skin work was installed to both halves, in										
the damaged area. Repair dope in accordance with AC43.13-14, Chapter 2.										
4. Unit Identification in the state of the s										
Unit		Make			Model			Serial No.		Alteration
AIRFRAME		Revi Toldisolo A. Mica (As described in Item Fabove) The Lorente Lact 1867 to 2012 to 2012 in 1867 to 2012 in								
POWERPLAN	JT	ons i	Sydemon feath		Reduinitie Offi	OS TA	okki zaidos	e in the second	: # #(PP)	•
PROPELLER			Hiller HA .T			•				
APPLIANCE		Туре		. <u>-</u>		23.7.3. 3.3.			343,6163	· · · · · · · · · · · · · · · · · · ·
		On the state of the second sec		و مانيا داخل مانيه المار والا	المراجع المراج		in the first the control of the second second			
		Manufacturer								
6. Conformity Statement										
							icate No.			
HENRY	K	RUZAKOWSKI OX 497			U.S. Certificated Mechanic			A+P267490854		
P.O. 1	30				Foreign Certificated Mechanic					
TAU	EPZ	NIER F. 33070			Certificated Repair Station Manufacturer					
D. I certif	fy tha	at the repair and/ made in accorda	or alteration made to	ements	it(s) identified in iter of Part 43 of the U.S	n 4 above a S. Federal	nd described on the Aviation Regulation	ne reverse ons and th	or attachmer at the inform	nts hereto ation
Date	ileu i	———————	d correct to the best	OI IIIY I		i i i : .				
Date MARCI+ 15, 1998 Signature of Authorized Individual										
				7. Ap	proval for Return To	Service				
Pursuant to the authority given persons specified below, the unit identified in item 4 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is APPROVED REJECTED										
1 1 .	AA F	It. Standards ctor	Manufacturer	X	Inspection Authoriza	ation	Other (Specify)			
	ΑΑ [Designee	Repair Station		Person Approved by Canada Airworthine					
Date of App	rova	I or Rejection	Certificate or Designation No.		Signature of Autho	rized Indiv	idual			
3/15/98 267490854 D. M.									1910	

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

RUDDER DAMAGE REPAIR

Repaired rudder damage by replacing damaged area with corrugated Republic Aircraft skin from stock that matched damaged area. Rudder is assembled in two halves, lengthwise. Rudder was disassembled in accordance with AC43.13-1A, Chapter 2, Section 3, and Paragraph d. Damaged area was removed and skin stock was installed to both halves, in the damaged area. Repair done in accordance with AC43.13-1A, Chapter 2, Section 3, Paragraph 99-c, d and Figure 2.18 (A) and Paragraph 100-e (2) a, b, c.

Rudder spar was damaged at the upper hinge attach point. A doubler was installed inside of the spar and riveted together. The middle hinge fitting uses a small backing plate for added stiffness. This was removed and installed a .051 2024T3 backing plate that measures 4 ¾" X 7" in length. This backing plate is permanently riveted to the spar. All work was done in accordance with AC43.13-1A, Chapter 2, Section 3, Paragraph 99 c, d, Paragraph 100 g, (1) a, b and Figure 2.25.

*** * * *