US Department

of Transportation Federal Aviation Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020

Office Identification

For FAA Use Only

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instruction

for each su	sition of this form. This report is requiuch violation (Section 901 Federal Av	red by law (4	9 U.S.C. 1421). Fa f 1958).	tilure to r	eport can result in	a civil pen	alty not to ex	ceed \$1,000	
1. Aircraft	Make Republic			Model RC-3 Seabee					
	Serial No. 387		Nationality and Registration Mark 398CM						
2. Owner	Name (As shown on registration of Charliemax Corp.	certificate)	Address (As shown on registration 1830 Lindberg Lane, Daytona Beach, FL 32124				certificate)		
-,		3.	For FAA Use On	ly					
	accve of the contract of the c	rson author	herein compiles rements and is a rements and is a recreated for F.A. F. 43	conform .Z(b) &	ity inspection (c)			•	
	// 4. Unit Iden			n	<u> </u>	5. Type			
Unit	Make		Model		Serial No	o.	Repair	Alteration	
NRFRAME		(As describe	ed in Item 1 above	·)					
OWERPLANT									
909ELLER									
PFLIANCE	Type Manufacturer								
		6. Co	nformity Stateme	ent		<u> </u>			
. Agency's Na	ame and Address	-	Kind of Agency			C. Certif	icate Nc.		
Don Wallace dba W.E. Aerotech Services Inc. 171 W Sanderson Way, Shelton WA			Y US Certificated Mechanic Foreign Certificated Mechanic Certificated Repair Station Manufacturer			552-76-1362			
	at the repair and/or alteration made to made in accordance with the require herein is true and correct to the best	ements or ex	ari ali critopii 🗙 🦼	above a Federal /	nd described on th Aviation Regulatio	ns and tha	or attachmen at the informa	its nereto ation	
2-20-	98	Sign	cature of Authoriz	ec Indiv	ıcual				
			l Ior Return To S						
dursuant to th	ne authority given persons specified of the Federal Aviation Administration	thelow the on and is	unit identified in	item 4 C RE	was inspected in JECTED	the mann	er prescribe	פין: יל ט	
FAA F Insced	It. Standards Manufacturer	X Insce	estion Authorizatio	រា	Cther (Scecify;				
<u> </u>	esignee Recair Station	Perso	on Approved by Trada Airworthiness (ansport Broup					
e of Approval	Designation No.		ature of Authorize	d Individ	20:31				

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished (If more space is required, attach additional sheets, Identify with aircraft nationality and registration mark and date work completed.)

Installed Airwolf Filter Corp. Remote Oil Filter Kit PN AFC-K007-D including Champion Spin On Filter PN CH48109. This kit and installation instructions were prepared specifically for the Lycoming IGSO-480 installed on Republic RC-3 Ser. #387 (ref. Airwolf invoice and correspondence dated 9-25-97). This Champion filter and Airwolf base adapter assembly are approved for installation on all Lycoming engines to 450 H.P. via Airwolf S.T.C. SA00024NW. The PN CON-10 Engine Adapter is approved for installation on all Continental engines to 450 H.P. via Airwolf S.T.C. SA00079NY. This PN CON-10 adapter was modified by Airwolf Corp. to be used on the Lycoming GSO-480. This installation was done in accordance with the instructions provided by the manufacturer specifically for this installation.

Installation of oil lines between the engine adapter and filter base adapter meet the requirements of FAR 23.1017(a), Oil Lines and Fittings and FAR 23.1301, Equipment - Function and Installation.

I have determined that this data is appropriate to the product being altered, is directly applicable to the alteration and is not contrary to the manufacturers / STC holders data. This alteration does not require any change to the approved maintenance and inspection procedures for this aircraft with the exception of oil filter screen inspections. Oil filter screen inspections will be performed by cutting open the Champion CH48109 filter and inspecting for metal contamination or any evidence that may indicate impending engine problems. Weighed aircraft and prepared weight and balance report (see weight and balance and equipment list dated 2-20-98).

END