

**SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES**

October 2005

Aircraft Section
SKY ENTERPRISES, Inc.

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; T.C. A-769	SA00061LA	Installation of JPI digital tachometer. Issued 3/29/95.	ANM-100L	J P Instruments 9621 Bay Meadow Dr. Huntington Beach, CA 92646 United States
RC-3; T.C. A-769	SA00068LA	Installation of tail wheel adapter ring. Issued 4/11/2002.	ANM-100L	R-R-R-Russ Aircraft P.O. Box 224 Avery, CA 95224 United States
RC-3; T.C. A-769	SA00081NY	Installation of carburetor ice detector. Amended 12/7/1995.	ANM-100S	Lamar Technologies Corp. 14900 40th Avenue NE Maysville , WA 98271 United States
RC-3; T.C. A-769	SA00194BO	Installation of P/N 2042 Landing Gear Warning System for amphibian aircraft. Issued 3/1/2004	ANE-150	Aircraft Components Inc 1040 Harbor Lake Drive Safety Harbor, FL 34695 United States
RC-3, Seabee; T.C. A-769	SA00332SE	Installation of a Lycoming GSO0-480-B2C6 engine and a Hartzell HC-A3CF-23L propeller. Issued 4/26/1996	ANM-100S	W.E. Aerotech Services West 171 Sanderson Way Shelton, WA 98584 United States
RC-3, Seabee; T.C. A-769	SA00432SE	Installation of EGT 701 series fuel flow instrument. Issued 2/9/2004	ANM-100L	J P Instruments P.O. Box 7033 Huntington Beach, CA 92615 United States
RC-3; T.C. A-769	SA00680SE	Installation of Electronics International model UBG-16 or UGB-16T bar graph engine analyzer. Issued 7/8/2005	ANM-100S	Electronics International 2092 NW Alocek #523 Hillsboro, OR 97124 United States
RC-3; T.C. A-769	SA00721SE	Installation of a Keith Products air conditioning system Issued 7/23/1999	ANM-100S	W.E. Aerotech Services, Inc. W. 171 Sanderson Way Shelton, WA 98584 United States
RC-3; T.C. A-769	SA00722SE	Installation of an S-TEC two axis auto pilot system with electric trim and associated hardware.	ANM-100S	W.E. Aerotech Services, Inc. W. 171 Sanderson Way Shelton, WA 98584 United States
RC-3; T.C. A-769	SA00861SE	Installation of J.P. Instruments (JPI) fuel flow indicating system in Accordance with JPI. Issued 2/9/2004	ANM-100L	J P Instruments 9621 Bay Meadow Drive Huntington Beach, CA 92646 United States
RC-3; T.C. A-769	SA00954SE	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System In accordance with JPI. Issued 8/11/2003	ANM-100L	J P Instruments P.O. Box 7033 Huntington Beach, CA 92615 United States

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; T.C. A-769	SA01860NY	Installation of Graphic Engine Monitors (GEM) Models GEM-610 and GEMINI 1200. Issued 08/22/2003	ANE-170	Insight Instrument Corporation Box 122 Ft Eric, Ontario L2A 5M6 Canada
RC-3; T.C. A-769	SA02012AT	Installation Lycoming model GO-480-G2D6 engine and Hartzell model HC-A3MVF-3L propeller with LMV-9333N-5 blades. Issued 10/20/1999	ACE-115A	Murphy John B/Stringer Dorothy E 2075 Big Nose Drive Centre, AL 35960 United States
RC-3; T.C. A-769	SA02033AT	Modification to install an air-oil separator to prevent oil from being aspirated from the engine breather line. Issued 06/29/2005	ACE-115A	M-20 Oil Separators LLC 5612 NW 38 th Terrace Boca Raton, FL 33496-2719 United States
RC-3; T.C. A-769	SA02520AT	Installation of M-20 Oil Separator model 600-WP Issued 05/30/2002	ACE-115A	M-20 Oil Separators LLC 5612 NW 38 th Terrace Boca Raton, FL 33496-2719 United States
RC-3; T.C. A-769	SA1-18	Increasing the wing span 16 inches and incorporating wing tip spill plates. Issued 1/1/1960	ANE-150	Ned C. Rice 470 Silver Lane East Hartford, CT 06108 United States
RC-3; T.C. A-769	SA1153NW	Installation of a pitot/static head (Piper P/N 69041-05) and associated systems in accordance with Simuflight, Seattle Installation Drawing No. SP-1000 Issued 06/25/2004	ANM-100S	McHugh Aviation Inc. 3763 Image Drive Anchorage, AK 99504 United States
RC-3; T.C. A-769	SA1158NW	Installation of an auxiliary electric Hydraulic Pump System in accordance with Simuflight Seattle Modification and Installation Procedure Instruction Report SS-900 Issued 06/25/2004	ANM-100S	McHugh Aviation Inc. 3763 Image Drive Anchorage, AK 99504 United States
RC-3; T.C. A-769	SA1244NW	Installation of a machined wrought 2024-T351 tail wheel collar (Republic P/N 126) in place of a die-forged 2014-T6 original part in accordance with Simuflight Seattle Drawing Number SP-2000 Issued 06/25/2004	ANM-100S	McHugh Aviation Inc. 3763 Image Drive Anchorage, AK 99504 United States
RC-3; T.C. A-769	SA1261NW	Installation of a remanufactured lower wing strut fittings in accordance with Simuflight, Seattle Report No. SP-300 and Drawing No. SP-3000 Issued 06/25/2004	ANM-100S	McHugh Aviation Inc. 3763 Image Drive Anchorage, AK 99504 United States
RC-3; T.C. A-769	SA1315WE	Installation of Tri-Star Corp. mixture monitor (exhaust gas temperature probe, gage, and Selector). Issued 10/10/1985	ANM-100D	Universal Corporation 730 Independent Avenue Grand Junction, CO 81505 United States
RC-3; T.C. A-769	SA1455NM	Installation of a flame proof auxiliary heater-dryer Model 12-1600. Reissued 12/11/85.	ASW-190	D.C. Thermal, Inc. 311 South 16 th LaPorte, TX 77571 United States
RC-3; T.C. A-769	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	ANM-100L	K S Avionics 18145 Judy Street Castro Valley, CA 94546 United States

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; <i>T.C. A-769</i>	SA157NE	Installation of Graphic engine monitor system Model GEM-602 S/N 403 and GEM-603 S/N 001126 and subsequent. Amended 10/18/96.	ANE-170	Insight Instrument Corp. Box 194, Ellicott Station Buffalo, NY 14205-0194 United States
RC-3; <i>T.C. A-769</i>	SA1626NM	Installation of Electronics Intn'l digital EGT/CHT instruments and accessories. Amended 3/9/93.	ANM-100S	Electronics International, Inc. 5289 N.E. Elam Young Parkway, #G200 Hillsboro, OR 97124 United States
RC-3; <i>T.C. A-769I</i>	SA17CE	Extension of each wing tip 24-inches.	ANM-100S	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028 United States
RC-3; <i>T.C. A-769</i>	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	ANM-100L	K S Avionics 18145 Judy Street Castro Valley, CA 94546 United States
RC-3; <i>T.C. A-769</i>	SA215SO	Extended wing tips.	ACE-115A	Gulf Airways, Inc. P.O. Box 1126 Fort Myers, FL 33902 United States
RC-3; <i>T.C. A-769</i>	SA2386WE	Installation of Simuflight, Seattle Part No. SP-4000-1 and SP-4000-2 Fiberglass Camber Wing Tips in accordance with Simuflight, Seattle Installation Instructions SP-400. Simuflight, Seattle FAA Approved Airplane Flight Manual Supplement Dated September 12, 1983 is required. Issued 6/25/2004	ANM-100S	McHugh Aviation Inc. 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA2586NM	Installation of J.P. Instruments temperature monitoring systems. Issued 6/17/1999	ANM-100L	J P Instruments 9621 Bay Meadow Drive Huntington Beach, CA 92646 United States
RC-3; <i>T.C. A-769</i>	SA2635NM	Modify airplane by extending wings and flaps 16 inches, and relocating ailerons 16 inches outboard on the wing in accordance with Simuflight Drawing Numbers SP-5000, Sheet 1, Revision 'A', dated May 18, 1984; or later FAA approved revisions. Issued 6/25/2004	ANM-100L	McHugh Aviation 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA282NW	Installation of Lycoming GO-480-B1D engine and Hartzell NC83X20-2CL propeller. Issued 4/13/76.	ANM-100S	S.T.C. Bee 10900 Rainier Ave. South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA3-28	J.F. Hamilton modified wing tips.	ACE-115C	Archie Keith Route 3 Ottawa, IL 61350 United States
RC-3; <i>T.C. A-769</i>	SA3-30	Modified spray rail with four foot addition to wing span.	ACE-115C	Miller Flying Service North Benton, OH 44449 United States
RC-3; <i>T.C. A-769</i>	SA3-365	Republic RC-3 starter system.	ACE-115C	Sentas Skyways Service City Airport Detroit, MI 48233 United States

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; <i>T.C. A-769</i>	SA-380	Fuel filler door assembly installation. Amended 1/7/75.	ACE-115C	John E. Ayer 405 South Third Street Le Sueur, MN 56058 United States
RC-3; <i>T.C. A-769</i>	SA3-88	Hartzell propeller HC-13X20-54 installation. Amended 1/7/75.	ACE-115C	John E. Ayer 405 South Third Street Le Sueur, MN 56058 United States
RC-3; <i>T.C. A-769</i>	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	ANE-170	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743 United States
RC-3; <i>T.C. A-769</i>	SA334SW	Installation of InterAv Alternator. Reissued 7/20/81.	ASW-190	InterAv, Inc. P.O. Box 16714 100 E. Nakoha San Antonio, TX 78216 United States
RC-3; <i>T.C. A-769</i>	SA3601SW	Installation of replacement tail wheel tire and tail wheel rim assembly. Issued 4/10/86.	ASW-190	Edmond F. Freeman 342 Westridge Drive Abilene, TX 79605 United States
RC-3; <i>T.C. A-769</i>	SA374NW	Installation of S.T.C. Bee, Inc. Model 1-TP-1 model instrument panel kit. Issued 11/1/76.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Ave South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA392NW	Installation of flush fuel fill. Issued 12/28/76.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Ave South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA393NW	Rework of main step gusset. Issued 12/28/76.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Ave South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA394NW	Installation of Model 2-DT droop wing tips.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Ave South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA395NW	Reshape rear cabin side windows Issued 12/28/76.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Ave South Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA3968NW	Installation of Fuel Cell Issued 10/25/1987	ANM-100S	Aero Tech Services Inc. 8354 Secura Way Santa Fe Springs, CA 90670 United States
RC-3; <i>T.C. A-769</i>	SA39CH	Installation of amphibian landing gear position advisory system.	ACE-115C	Lake and Air Inc. 550 Flying Cloud Drive Chaska, MN 55318 United States

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; <i>T.C. A-769</i>	SA4302NM	Installation of Electronics Intr'l digital automatic engine analyzers. Amended 3/5/93.	ANM-100S	Electronics International, Inc. 5289 N.E. Elam Young Parkway, #G200 Hillsboro, OR 97124 United States
RC-3; <i>T.C. A-769</i>	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	ANE-170	Aircraft & Rotorcraft 2 Middle Cross Road Shoreham, NY 11786-1440 United States
RC-3; <i>T.C. A-769</i>	SA5422SW	Alternate tail wheel, tire, tube. Issued 5/12/83.	ASW-190	John R. Campbell 3524 Whitehall Dallas, TX 75229 United States
RC-3; <i>T.C. A-769</i>	SA5652NM	Installation of a Lycoming TIO540-A2B engine together with a Hartzell HC-E3YR-7LF/FLC8468-4R propeller. Reissued 3/31/92.	ANM-100S	T.A.C., Inc. P.O. Box 1180 Blaine, WA 98230 United States
RC-3; <i>T.C. A-769</i>	SA5656NM	Installation of burglar alarm system Amended 7/21/1993	ANM-100S	Thompson Harold S. P.O. Box 2361 Gig Harbor, WA 99206 United States
RC-3; <i>T.C. A-769</i>	SA5684NM	Installation of Lycoming GSO/IGSO-480 engine; Hartzell HC-A3V20 propeller; new nacelle and engine mount; modified front and rear spar and aft firewall; and associated systems. Issued 2/19/92.	ANM-100S	McHugh Aviation 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA5734NM	Installation of a GSO-480-B1G6 engine and a HC-A3V20-3L/LV8433N propeller and to increase the take off weight to 3254 lbs.	ANM-100S	Donald V. Kyte 216 146 th Street SW Lynnwood, WA 98037 United States
RC-3; <i>T.C. A-769</i>	SA575NW	Installation of longitudinal step kit. Issued 3/16/78.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Avenue Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA576NW	Install disc brake system. Issued 3/14/78.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA5771NM	Modify aft fuselage bulkhead and reroute aileron cables in order to extend baggage compartment floor. Amended 12/29/94.	ANM-100S	McHugh Aviation 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA57NE	Installation of Stewart-Warner Model Model 940-F-12 heater. Issued 3/30/82.	ANE-150	Stol Aircraft Corp. P.O. Box 175 Norwood Arprt Norwood, MA 02062 United States

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	ACO	STC HOLDER
RC-3; <i>T.C. A-769</i>	SA5924NM	Installation of RPM instrument. Amended 6/3/94.	ANM-100S	Electronics International 5289 Elam Young Pkwy #G200 Hillsboro, OR 97124 United States
RC-3; <i>T.C. A-769</i>	SA5925NM	Installation of oil pressure/ temperature instrument.	ANM-100S	Electronics International 5289 Elam Young Pkwy #G200 Hillsboro, OR 97124 United States
RC-3; <i>T.C. A-769</i>	SA613NW	Install 28-volt electrical system Issued 6/1/78.	ANM-100S	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178 United States
RC-3; <i>T.C. A-769</i>	SA615NW	Installation of Lycoming GO-435-C2B, GSO-IGSO-480 series, and GO-IGO-480 series engine with Hartzell HC-A2V20 and HC-A3VF series propellers; new nacelle and engine mount; modified front and rear spar and aft firewall; and associated systems. Amended 2/28/92.	ANM-100S	McHugh Aviaiton 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA815NW	Installation of Cleveland disc type brakes. Issued 7/25/79.	ANM-100S	McHugh Aviaiton 3763 Image Drive Anchorage, AK 99504 United States
RC-3; <i>T.C. A-769</i>	SA821EA	Installation of Stol Aircraft Corporation fuel cell. Issued 5/19/70.	ANE-150	Stol Aircraft Corporation P.O. Box 175 Norwood Arpt Norwood, MA 02062 United States
RC-3; <i>T.C. A-769</i>	SA853EA	Installation of Stol Aircraft Corporation electric hydraulic pump system. Issued 11/19/70.	ANE-150	Stol Aircraft Corporation P.O. Box 175 Norwood Arpt Norwood, MA 02062 United States
RC-3; <i>T.C. A-769</i>	SA915NW	Installation of a South Wind Model 940 combustion heater. Issued 4/4/80.	ANM-100S	McHugh Aviaiton 3763 Image Drive Anchorage, AK 99504 United States