US Department of Transportation Federal Aviation

Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved	
OMB No. 2120-0020	C

For FAA Use Only

Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1,000 for each such violation (Section 901 Federal Aviation Act of 1958).

ior each su	ich violation (Sec	nion gut Federal Avia	tion A	ct of '	1958).						
	Make]	Republic			Mod	iel	RC-3		- - <u> </u>	<u></u>	
1. Aircraft	Serial No.			Nationality and Registration			n Mark	<u>. </u>			
		N5166B									
	Name (As sho	Name (As shown on registration certificate) Address (As shown on registration certificate)							certificate)		
2. Owner	Day	vey Darrell L		6613 Santa Rosa Rd							
	Davey Deborah A				Camarillo Ca 93012-5672						
wavey weblank 23				3.	3. For FAA Use Only						
							- ·		<u> </u>		
											
					Unit Identification		······································		5. Type		
Unit		Make			Model		Serial No).	Repair	Alteration	
			· <u> </u>				<u></u>				
AIRFRAME)	As des	cribe	d in Item 1 above) 🗻	~~~	······	,			
				·	· ·=-· _,				 		
POWERPLANT	Tyroom	Lycoming			~ 400		~ ~ ~ .	_			
	Lycom				J-480 A LA	.6	L-212-44				
ROPELLER											
	Туре				······································						
PPLIANCE	Manufacturer										
	Manacatare										
			(6. Co	nformity Statement	<u> </u>			<u>1_, , , , , , , , , , , , , , , , , , , </u>	<u> </u>	
A. Agency's N	lame and Addres	S			Kind of Agency			C. Certi	ificate No.	 · · · · · · · · · · · · · · · ·	
Kenneth L. Thompson PO Box 411 Vineburg, Ca. 95487				N/	U.S. Certificated Mech				545767051		
				-		reign Certificated Mechanic					
				Certificated Repair Station Manufacturer							
		/or alteration made to	thour	it(e) i	<u> </u>	01:00		<u> </u>	· · · · · · · · · · · · · · · · · · ·		
nave bee	n made in accord	iance with the require	ements	of Pa	art 43 of the U.S. Fed	leral A	No described on the Aviation Regulation	ne reverse ons and th	or attachment at the information	nts hereto ation	
ate	rierein is true ar	nd correct to the best	ot my		<u> </u>		<u> </u>	<u> </u>			
9-20-49				Signature of Authorized Individual							
					1cm/	les	ruper				
			7. Ap	prova	al for Return To Servi	ce			· · · · · · · · · · · · · · · · · · ·		
Pursuant to Administrato	the authority giver of the Federal	en persons specified Aviation Administration	belov on and	w, the	e unit identified in ite APPROVED	em 4	was inspected in JECTED	the man	ner prescribe	ed by the	
	Flt. Standards ector	Manufacturer		Insp	nspection Authorization Other (Specify)						
	Designee	Repair Station		Pers Cana	on Approved by Trans ada Airworthiness Gro	port up					
	al or Rejection	Certificate or Designation No.	- -	Sign	nature of Authorized	ndivid	dual		· · · · · · · · · · · · · · · · · · ·		
7-20-99 552273581				Bouglas P Smith							

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

B. Description of Work Accomplished (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)
in more space to required, and on accomminations. Including their ancian nationality and registration main and date work completed.)
RC-3 N5166B S/N 1000
Installed propeller governor adapter with a combination adapter/valve to provide propeller reversing control in accordance with Simuflight, Seattle, Drawing List SS-6000, Revision D, dated 11-16-90 and STC# SE914NW.
Additional Sheets Are Attached